



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 23, 2012

Reviewed: 

Mine Name: Lost Sheep Mine	Permit Number: S/023/0029
Operator Name: Michael Provstgaard	Inspection Date: August 23, 2012
Inspector(s): Wayne Western	Time: 3:00 – 3:35 pm
Other Participants: none	Mine Status: ACT
Weather Condition: Clear skies and hot	Last Inspection: October 26, 2011
Bond Renewal Date: March 13, 2015	Bond Amount: \$11,400.00
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: no production since permitted in 2009	Acreage: 2 Acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

Bond, permit fees and annual reports are all current.

Rule R647-3-113.4 requires that the Operator provide written notice if mining is suspended for more than five years. If no mining occurs in 2012 then the Operator must inform the Division of the suspension of mining activities.


Not much has changed since the last inspection. The site is stable and secured.

Conclusions and Recommendations:

The main concern is lack of activity on the site and the future need for reclamation if no mining occurs.

Directions to Site:

Inspector's Signature




WHW:

cc: (OPERATOR)

Jerry Mansfield

O:\M023-Juab\S0230029-LostSheep\inspections\Insp-08232012.doc



Proof of labor on the claims



Mine site looking west



Mine site



Mine site from entrance